


# Sady závitorezných nástrojů



## M


M 1-1,2-1,4-1,7-2,0-2,3-2,6	No. 0	16x5	20x5	20x7	No. 1	48002
M 3-3,5-4-5-6-8-10	No. 1	25x9	30x11			
M 3-4-5-6-7-8-9-10-11-12	No. 1 + 2	20x5	20x7	25x9	No. 1	48003
		30x11	38x14			
M 5-6-7-8-9-10-11-12	No. 1 + 2	20x7	25x9		No. 1	48004
		30x11	38x14			
M 5-6-7-8-9-10-11-12-14-16	No. 1 + 3	20x7	25x9	30x11	No. 1	48005
M 18-20		38x14	45x18			
M 3-4-5-6-8-10-12-14-16-18-20	No. 1 + 4	20x5	20x7	25x9		48006
M 22-24		30x11	38x14	45x18		
		55x22				
M 5-6-8-10-12-14-16-18-20-22	No. 1	20x7	25x9	30x11		48007
M 24-27-30	No. 3 + 5	38x14	45x18	55x22		
		65x25				

## Mf

Mf 3x0,35-4x0,5-5x0,5	No. 1 + 2	20x5	25x9	30x11	No. 1	48010
Mf 6x0,75-8x0,75-8x1,0	No. 1	38x10				
Mf 10x1,0-12x1,5						
Mf 6x0,75-8x0,75-8x1,0-10x1,0	No. 1 + 3	20x7	25x9	30x11		48011
Mf 12x1,0-12x1,5-14x1,25-14x1,5		38x10	45x14			
Mf 16x1,5-18x1,5-20x1,5						
Mf 6x0,75-8x0,75-8x1,0-10x1,0						48012
Mf 12x1,0-12x1,5-14x1,25-14x1,5	No. 1 + 4	20x7	25x9	30x11		
Mf 16x1,5-18x1,5-20x1,5-22x1,5		38x10	45x14	55x16		
Mf 24x1,5						

## G (BSP)

G 1/8-1/4-3/8-1/2-3/4-1"	No. 1 + 3 + 5	30x11	38x10	45x14		48020
		55x16	65x18			
G 1/8-1/4-3/8-1/2-5/8-3/4-7/8-1"	No. 1 + 3 + 5	30x11	38x10	45x14		48021
		55x16	65x18			
G 1/4-3/8-1/2-3/4-1"-1.1/4-1.1/2	No. 2 + 4 + 7	38x10	45x14	55x16		48022
		65x18	75x20	90x22		



## BSW

BSW 1/8-3/16-1/4-5/16-3/8-7/16-1/2	No. 1 + 2	20x5 30x11	20x7 38x14	25x9	No. 1	48030
BSW 1/4-5/16-3/8-7/16-1/2	No. 1 + 2	20x7 38x14	25x9	30x11		48031
BSW 1/4-5/16-3/8-7/16-1/2-5/8-3/4	No. 1 + 3	20x7 38x14	25x9	30x11 45x18		48032
BSW 1/4-5/16-3/8-7/16-1/2-5/8	No. 1 + 4	20x7 38x14	25x9	30x11 45x18		48034
BSW 3/4-7/8-1"				55x22		
BSW 1/4-5/16-3/8-7/16-1/2-5/8-3/4	No. 1	20x7	25x9	30x11		48035
BSW 7/8-1"-1.1/8-1.1/4-1.3/8-1.1/2	No. 3 + 5	38x14	45x18	55x22 65x25		

## BSF

BSF 1/4-5/16-3/8-7/16-1/2	No. 1 + 2	20x7 38x10	25x9	30x11	No. 1	48041
BSF 1/4-5/16-3/8-7/16-1/2-5/8-3/4	No. 1 + 3	20x7 38x10	25x9	30x11 45x14		48042
BSF 1/4-5/16-3/8-7/16-1/2-5/8	No. 1 + 4	20x7 38x10	25x9	30x11 45x14		48044
BSF 3/4-7/8-1"				55x16		

## BSW / BSF


BSW/BSF 1/4-5/16-3/8-7/16-1/2	No. 1 + 3	20x7	25x9	30x11		48046
BSW/BSF 5/8-3/4		38x14	45x18			

## NPT

NPT 1/8-1/4-3/8-1/2-3/4-1"	No. 1 + 3 + 5	30x11 55x22	38x14	45x18 65x25		48025
NPT 1/8-1/4-3/8-1/2-3/4-1"	No. 2 + 4 + 7	30x11	38x14	45x18		48027
NPT 1.1/4-1.1/2-2"		55x22	65x25	75x30 90x36		

## UNC

UNC 1/4-5/16-3/8-7/16-1/2	No. 1 + 2	20x7 38x14	25x9	30x11	No. 1	48050
UNC 1/4-5/16-3/8-7/16-1/2-5/8-3/4	No. 1 + 3	20x7 38x14	25x9	30x11 45x18		48051
UNC 1/4-5/16-3/8-7/16-1/2-5/8	No. 1 + 4	20x7 38x14	25x9	30x11 45x18		48053
UNC 3/4-7/8-1"				55x22		
UNC 1/4-5/16-3/8-7/16-1/2-5/8-3/4	No. 1	20x7	25x9	30x11		48054
UNC 7/8-1"-1.1/8-1.1/4-1.3/8-1.1/2	No. 3 + 5	38x14	45x18	55x22 65x25		




## UNF


UNF 1/4-5/16-3/8-7/16-1/2	No. 1 + 2	20x7 25x9 30x11 38x10	No. 1	48060
UNF 1/4-5/16-3/8-7/16-1/2-5/8-3/4	No. 1 + 3	20x7 25x9 30x11 38x10 45x14		48061
UNF 1/4-5/16-3/8-7/16-1/2-5/8	No. 1 + 4	20x7 25x9 30x11		48063
UNF 3/4-7/8-1"		38x10 45x14 55x16		

## UNC / UNF


UNC/UNF 1/4-5/16-3/8-7/16-1/2	No. 1 + 3	20x7 25x9 30x11		48066
UNC/UNF 5/8-3/4		38x14 45x18		



P.V.1	M 3-4-5-6-8	2,5/3,3/4,2/5,0	No. 1	20x5 20x7 25x9	No. 1	49101
	M 10-12	6,8/8,5/10,2	No. 2	30x11 38x14		
<b>HSSE</b>	M 3-4-5-6-8	2,5/3,3/4,2/5,0	No. 1	20x5 20x7 25x9	No. 1	49151
	M 10-12	6,8/8,5/10,2	No. 2	30x11 38x14		
<b>LH</b>	M 3-4-5-6-8	2,5/3,3/4,2/5,0	No. 1	20x5 20x7 25x9	No. 1	49171
	M 10-12	6,8/8,5/10,2	No. 2	30x11 38x14		
	M 3-4-5-6-8	2,5/3,3/4,2/5,0	No. 1	20x5 20x7 25x9		49111
	M 10-12	6,8/8,5/10,2	No. 2	30x11 38x14		




	M 3-4-5-6-8		No. 1	20x5 20x7 25x9		49107
	M 10-12		No. 2	30x11 38x14		
P.V.2	M 3-4-5-6-8-10-12-14		No. 1	20x5 20x7 25x9	No. 1	49201
	M 16-18-20		No. 3	30x11 38x14 45x18	No. 2	
<b>HSSE</b>	M 3-4-5-6-8-10-12-14		No. 1	20x5 20x7 25x9		49251
	M 16-18-20		No. 3	30x11 38x14 45x18		
<b>LH</b>	M 3-4-5-6-8-10-12-14		No. 1	20x5 20x7 25x9		49271
	M 16-18-20		No. 3	30x11 38x14 45x18		
P.V.3	M 3-4-5-6-8-10-12-14		No. 1	20x7 25x9 30x11	No. 1	49301
	M 16-18-20		No. 3	38x14 45x18	No. 2	
P.V.5	M 3-4-5-6-8-10-12-14		No. 1	20x5 20x7 25x9		49205
	M 16-18-20		No. 3	30x11 38x14 45x18		




P.V.22	M 3-4-5-6-8	2,5/3,3/4,2/5,0	No. 1.1/2			49510
	M 10-12	6,8/8,5/10,2 mm				
P.V.23	M 3-4-5-6-8	2,5/3,3/4,2/5,0	No. 1.1/2		No. 1	49511
	M 10-12	6,8/8,5/10,2 mm				






P.V.12 M 3-4-5-6-8-10-12 No. 1.1/2 25x9 No. 1 49501



P.V.97 M 3-4-5-6-8-10-12 49521

P.V.98 **HSSE** M 3-4-5-6-8-10-12 49522

P.V.99 M 3-4-5-6-8-10-12 49520




P.K.20 M 3-4-5-6-8-10-12 No. 1.1/2 47001

P.K.21 M 3-4-5-6-8-10-12 No. 1.1/2 No. 1 47005


**HSSE** M 3-4-5-6-8-10-12 No. 1.1/2 No. 1 47055

**LH** M 3-4-5-6-8-10-12 No. 1.1/2 No. 1 47075




M 3-4-5-6-8-10-12 2,5/3,3/4,2/5,0/6,8/8,5/10,2 mm No. 1.1/2 No. 1 47605

M 3-4-5-6-8-10-12 2,5/3,3/4,2/5,0/6,8/8,5/10,2 mm No. 1.1/2 47601



P.K.85 M3-4-5-6-8-10 2,5/3,3/4,2/5,0/6,8/8,5 80501



Do průchozí díry B M 3-4-5-6-8-10-12 80500

Do průchozí díry B-AZ M 3-4-5-6-8-10-12 80900

Do slepé díry C/35° M 3-4-5-6-8-10-12 80700



M 1-1,2-1,4-1,7 No. 0 48001

M 2,0-2,3-2,6